



Attorney Docket No. 2153.1002 (formerly 1076.1092)

CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Hiroyuki TSUJIMOTO

Application No.: 10/725,587

ATTENTION

Confirmation No.: 3452

CERTIFICATE OF CORRECTION

Filed: December 3, 2003

BRANCH

Certificate

U.S. Patent No.: 7,724,689

OCT 22 2010

Issued: May 25, 2010

of Correction

For: INTERFACE DEVICE AND INTERFACE DEVICE CONTROL METHOD

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322/1.323, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One error shown on the attached Form PTO-1050 is or are within the responsibility of the patentee(s); each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

Date: October 19, 2010

By: *David M. Pitcher*
David M. Pitcher
Registration No. 25,908
10/21/2010 EKUBAY1 00000000 7724689
100.00 OP

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,724,689

DATED : May 25, 2010

INVENTOR(S) : Hiroyuki TSUJIMOTO

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 12, Line 30 delete "device" and insert --devices--.

Column 11, Line 45 delete "bust" and insert --bus--.

Column 12, Line 30 delete "the least" and insert --the at least--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY
1201 New York Avenue, N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,724,689

No. of add'l copies
@ 304 per page